

CONSUMER
PRODUCTS

MATERIAL SAFETY DATA SHEET

AIRWICK INDUSTRIES, INC.
CARLSTADT, NEW JERSEY 07072Date: October, 1985
Supersedes: R.T. French MSDS

Emergency Telephone Number:

201-933-8200

TRADE NAME BRASSO

PRODUCT TYPE Multipurpose Metal Polish (Pewter, Brass,
Copper, Stainless Steel, Chrome)

I. PHYSICAL DATA

BOILING POINT (°F)	318	FREEZING POINT (°F)	N/A
SPECIFIC GRAVITY (H ₂ O=1)	0.97	SOLUBILITY IN WATER, % by wt. at 20°C	Insoluble
PERCENT VOLATILES BY VOLUME	~ 70	pH (as is)	N/A
APPEARANCE AND ODOR	Tan with ammonia odor		
OTHER	N/A*		

II. HAZARDOUS INGREDIENTS

CHEMICAL OR COMMON NAME	CAS #	%	PEL OR TLV	PRIMARY HAZARD
petroleum distillate (Stoddard Solvent)	8032-41-3	~65	100 ppm	Combustible

III. FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (°F) (test method)	105 (S.C.C.)	FLAME EXTENSION	N/A
FLAMMABLE LIMITS IN AIR, % by volume	N/A	LOWER	N/A
		UPPER	N/A
EXTINGUISHING MEDIA	Foam, Dry chemical, CO ₂ , water spray or fog. Use of a direct stream of water can spread burning liquid.		
SPECIAL FIRE FIGHTING PROCEDURES	None		
UNUSUAL FIRE AND EXPLOSION HAZARDS	None		

*N/A - Not applicable.

BRASSO

IV. HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE

Ingestion: Local irritation, vomiting, diarrhea, drowsiness, rapid
breathing. Aspiration may occur.
Eyes: Irritant
Skin: May cause irritation on prolonged contact.
Inhalation: Respiratory irritation, headache, dizziness, nausea,
stupor.

EMERGENCY AND FIRST AID PROCEDURES

Ingestion: Do not induce vomiting. Give water. Call a physician.
Eyes: Flush with water for 15 minutes. Call a physician.
Skin: Wash with soap and water.
Inhalation: Remove to fresh air. Give artificial respiration if
necessary.

V. REACTIVITY DATA

STABILITY	Unstable Stable	Conditions To Avoid	Heat, spark, open flame.
INCOMPATIBILITY (Materials To Avoid)	Oxidizers such as chlorine, oxygen and strong oxidizing acids as nitric and sulfuric.		
HAZARDOUS DECOMPOSITION PRODUCTS	CO, CO ₂		
HAZARDOUS POLYMERIZATION	May Occur Will Not Occur	Conditions To Avoid	None

VI. SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED	Eliminate sources of heat or ignition. Provide adequate ventilation. Pick up excess with absorbent material, and put in disposable container.
--	---

WASTE DISPOSAL METHOD	Discard according to local, state and federal regulation.
-----------------------	---

VII. SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify Type)		N/A					
VENTILATION	Local Exhaust	N/A	Mechanical (General) Sufficient	Special	N/A	Other	N/A
PROTECTIVE GLOVES	Impervious		EYE PROTECTION	Safety glasses			
OTHER PROTECTIVE CLOTHING OR EQUIPMENT		N/A					

VIII. SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN
IN HANDLING AND STORAGE Store at ambient temperature. Keep container closed when not in use.
Store away from heat, flame, sources of ignition. Combustible.

OTHER

N/A